INDIAN INSTITUTE OF SCIENCE EDUCATION AND RESEARCH

PUNE

CLARIFICATION ON TENDER NUMBER - IISER-PUR-0022-0024-19

ITEM DESCRIPTION- PROCUREMENT OF 2U RACK SERVER

Refer our Press Tender Notice No.IISER/S&P/3/19 dated 17.6.2019 for procurement of 2U Rack Server. Tender Reference Number – IISER-PUR-0022-0024-14.

Pre-Bid meeting was held on June 24th , 2019 at 3.00 PM and minutes of meeting is as under.

At the outset, on behalf of Chairman, Assistant Registrar (S&P) welcomed all the Members and the representative of the Prospective Bidders and briefed in general the scope of the Project. The indenting Officer was requested to read out the clarification sought by the Prospective Bidders and replied thereto as detailed in Annexure -II

The representatives present were satisfied with the replies given and it was informed that the corrections / additons / clarifications given, as discussed during the Pre-Bid Conference would be hosted on the website of IISER Pune and all the Prospective Bidders are required to take cognizance of the proceedings of the Pre-Bid Conference before submitting their bids as stipulated in the Bidding Documents.

The other terms & conditions of the notice issued on our IISER website www.iiserpune.ac .in will remain unchanged. No more correspondence in this regard will be entertained

The meeting ended with vote of thanks to the Chair

Sd/-

24.6.2019   Assistant Registrar (S&P)

IISER PUNE

PRE-BID CONFERENCE FOR PROCUREMENT OF 2U RACK SERVER

TECHNICAL & COMMERCIAL QUERIES AND CLARIFICATION

TENDER NUMBER - IISER-PUR-0024-19   DATE : 24.6.19

Sr.No.	Query/Clarification Sought	Clarification / Amendment
1.	Are systems with power supply less than 800W acceptable?	Power supply with 800W or more are needed to allow for future upgradability.
2.	Are newer processors acceptable ?	Processors with number of cores and processor speed better than specified in the tender are acceptable.
3.	What type of SSD is required? Whether SATA is fine?	SATA SSD is acceptable.
4.	Is it necessary to install the software?	The following installation steps have to be completed to

		merge with the existing HPC system
		1. Install CentOS 7.2 OS on all the nodes.
		2. Configure to share the necessary folders.
		3. Install PBS (freely available) queuing software.
5.	What is meant by Onsite warranty?	Please refer Chapter 3, point 9 of tender document.
6	Who retains the responsibility of the warranty for the current cluster?	The responsibility of providing warranty of the current cluster is with the supplier of the current cluster.

Dr. Sreejith GJ   Dr. Arun M. Thalapillil   Mr. Goldi Misra   Salim Shaikh